

Job Description

Summary: *This position is a welder on the assembly line and will involve the set-up, programming, and operation of one or more robotic weld machines in the production of scroll compressors.*

Duties & Tasks

- Setup and operation of Panasonic welding equipment
- Setup and operation of PX top shell & separator plate welding equipment
- Annual weld certification for TAC and seam welding at OP70
- TPM of weld equipment, to include wire changes, liner replacements, nozzle cleaning and replacement
- Ensure production welds meet specifications
- Perform BIPROS cleanings on equipment and keep work area in a clean and orderly condition
- Identify and report problems with equipment to Manager and Maintenance
- Follow all prescribed and standard SAFETY regulations
- Ability to handle work pieces up to 50 pounds
- Work with Manufacturing Engineers to improve weld process control, reduce costs, and develop process improvements and/or process changes due to product changes.
- Accurately complete production and quality documentation both written and electronic
- Other duties as assigned by management

Competencies (Knowledge, Skills & Abilities): (adjust to specific job)

- HAUN Training preferred
- MIG & TIG Certified preferred
- Ability to be trained and certified in MIG and TIG may also be requested or required
- General knowledge of scroll compressor technology

Requirements:

- Must possess effective verbal and written communication skills.
- Must be able to effectively communicate and meet with other team members and supervisors with respect, courtesy, discretion, and sound judgement.
- Must be punctual and have a history of reliable attendance.
- Must possess the ability to work safely and effectively in a team manufacturing environment and be willing to assist other team members, as well as work collectively with others within the organization.
- Must possess good hand/eye coordination.
- Must demonstrate accuracy, responsibility, and thoroughness.

Work Environment:

- This job is performed in a manufacturing environment. Steel toed boots and safety glasses are required.

Physical Demands:

- While performing the duties of this job, the employee constantly is required to stand, walk, bend, stoop, use arms, hands and fingers. May be required to lift, push, and pull 30 or more pounds on a regular basis and occasionally up to 50 pounds.

Job Type: Full-time

Pay: \$15.00 per hour